

Subject Index

Subject	Page
Abrasion resistance	3-7
Abrasive blast cleaning - expendable abrasives	7-4 - 7-6
Abrasive blast cleaning - recyclable abrasives	7-6 - 7-8
Abrasive type and selection	7-10 - 7-12
Abrasive selection	7-10
Abrasive type	7-10
Characteristics	7-10
Chemical cleanliness	7-11
Cleaning/consumption rates	7-11
Dust generation	7-11
Embedment	7-11
Profile yield	7-12
Recyclable versus nonrecyclable	7-10
SSPC-AB 1	7-12
Additives	4-15 - 4-17
Antiskinning agents	4-16
Emulsion aids	4-16
Flow agents	4-16
Fungicides	4-16
Plasticizers	4-17
Thixotropes	4-16
UV absorbers	4-17
Adhesion, tape, tensile, interpretation of results	3-6 - 3-7
Adhesion testing	9-10 - 9-11
Air quality regulations	11-11 - 11-13
Air monitoring procedures	11-11 - 11-12
Baseline monitoring	11-12
Duration of monitoring	11-12
Establishing daily criterion for air monitoring	11-12
Limitation and use of NAAQS on paint removal projects	11-11
NAAQS for lead	11-11
National Ambient Air Quality Standards (NAAQS) for particulate matter	11-11
Placement of monitors	11-12
Volatile organic compounds (VOCs)	11-12 - 11-13
Airless spraying	8-5 - 8-6
Alkyds (see Binders, alkyd modifications)	
Ambient conditions, measurement of	9-2 - 9-3
Application assessing techniques (see Coating application)	
Application, airless spraying	8-5 - 8-6
Application, brush	8-1
Application, conventional spray	8-2 - 8-4

Subject	Page
Binders, Alkyd modifications, phenolic, vinyl, silicone, epoxy, urethane	4-3 - 4-4
Bituminous, hot melt, solvent cutback, water emulsion	4-5 - 4-6
Catalyzed epoxies, polyamine curing, polyamide curing, 100 percent solids, coal tar	4-7 - 4-9
Natural resins, rosins, shellacs, copals	4-3
Oil-based alkyds	4-3
Urethanes, isocyanates, polyols, acrylic, polyester, polyether, epoxy, vinyl, moisture-cured	4-9 - 4-10
Vinyl ester	4-10 - 4-11
Vinyls, vinyl chloride, vinyl butyral wash primer, vinyl chloride-vinyl acetate copolymers, waterborne vinyl	4-6 - 4-7
Waterborne acrylic emulsions, styrene acrylic, latex	4-4 - 4-5
Brush application	8-1
Brush-off blast cleaning (SSPC-SP 7)	7-12
Catalyzed epoxies, polyamine curing, polyamide curing, 100% solids, coal tar	4-7 - 4-9
Chemical resistance	3-8
Coal tar epoxy (see Binders, catalyzed epoxies)	
Coating application, methods of	8-1 - 8-8
Air-assisted airless spraying	8-6 - 8-7
Airless spraying	8-5 - 8-6
Brush application	8-1
Conventional spray application	8-2 - 8-5
Electrostatic spray	8-7 - 8-8
High volume-low pressure spraying	8-5
Plural component spray application	8-7
Roller application	8-1 - 8-2
Coating application techniques (assessment of)	9-7
Coating, identification of existing as lead containing	6-5 - 6-7
Coating, integrity of existing	6-4
Adhesion	6-4
Coating thickness	6-4
Substrate condition assessment	6-4
Coating material procurement by Contractor	3-2
Government Services Administration (GSA)	3-3
Rock Island Consolidated Paint Acquisition Contract (CENCR)	3-3
Coating material specification (see Specifications)	

Subject	Page	Subject	Page
Coating system, criteria for selecting	5-1 - 5-8	Compressed air cleanliness, assessing	9-3
Cathodic protection as an alternative . .	5-8	Confined space entry	10-9 - 10-11
Ease of application	5-8	Atmospheric testing	10-11
Identifying areas that cannot be		Confined space hazards	10-10
properly coated	5-4	Confined space program	10-9 - 10-10
Identifying coating application		Entry permit	10-11
alternatives	5-7	Self-contained breathing apparatus	
Identifying regulated requirements . . .	5-4	(SCBA)	10-10
Identifying surface preparation		Standby person	10-10
alternatives for maintenance	5-7	Training	10-10 - 10-11
Identifying surface preparation		Ventilation equipment	10-11
alternatives for new construction . . .	5-5 - 5-6	Contaminants, surface (see	
Identifying the service environment . .	5-1 - 5-4	Surface cleanliness)	
Maintainability	5-8	Conventional spray application	8-2 - 8-4
Supplier recommendation	5-8	Corrosion, causes	2-1
Coating system selection for ferrous		Corrosion, forms	2-2
components in fresh water	5-15 - 5-21	Concentration-cell corrosion	2-3
Ferrous metal components subject		Dealloying	2-3
to atmospheric weathering - normal		Erosion corrosion	2-3
and severe; immersion and frequent		Galvanic corrosion	2-2
wetting - fresh (inland waters);		General corrosion	2-2
prolonged wetting by splash, spray,		Intergranular corrosion	2-3
or condensation; penstocks,		Pitting corrosion	2-3
components include spiral cases,		Stress corrosion cracking	2-3
spiral cases extensions, draft tube		Corrosion mitigation, cathodic protection . .	2-5
liners, surge tanks, crest gates;		CP diagnostic software	2-7
control gates and valves of reservoir		Criteria for cathodic protection	2-7
outlet works; trash racks for water		Dielectric isolation	2-7
intakes; navigation lock gates, valves,		Impressed current systems	2-5 - 2-6
and miscellaneous submerged metal;		Monitoring effectiveness	2-6
navigation dam gates; freshwater		Sacrificial (galvanic) systems	2-5
(including potable) tanks; equipment		Systematic cathodic protection	
for local protection projects; floating		design procedure	2-6
plant (steel construction) operating		Corrosion mitigation, design considerations .	2-3 - 2-5
in fresh water; exterior surfaces of		Connection of old and new materials . .	2-4
steel hulls; interior of steel hulls;		Crevice corrosion	2-3
steel decks; exterior surfaces of		Electrical grounding	2-4
floating plant		Galvanized piping in 60 °C (40 °F)	
Coating system selection for ferrous		to 77 °C (170 °F) water	2-4 - 2-5
surfaces in seawater	5-21 - 5-22	Isolation of dissimilar metals	2-4
Cathodic protection (CP) and		Stainless steel—active and	
immersion in seawater	5-22	passive states	2-4
Ferrous metal surfaces of fixed		Stainless steel coupled to carbon steel .	2-4
structures	5-21 - 5-22	Unfavorable area differences	2-4
Steel pilings	5-22	Corrosion mitigation, inhibitors	2-7
Coating system selection for lead paint . . .	6-8	Corrosion mitigation, protective coatings . .	2-8
Coating systems for iron and steel pipe . . .	5-23	Corrosion resistance, salt fog,	
Black iron or steel pipe	5-23	prohesion, humidity	3-8
Galvanized pipe	5-23	Cost considerations for coating selection . . .	5-8 - 5-12
Coatings, other	4-24	Costs, impact of lead paint on surface	
Combustible/flammable liquids (see		preparation	6-7
Flammable/combustible liquids)		Environmental and worker protection . .	6-7
Commercial blast cleaning (SSPC-SP 6) . . .	7-12	Equipment	6-7

Subject	Page	Subject	Page
Labor	6-7	Inspection,	
Cure, evaluating	9-11	Ambient conditions, measurement of	9-2
Driers	4-12	Compressed air cleanliness, assessing	9-3
Dry coating thickness, destructive		Surface profile, measurement of	9-3 - 9-4
measurement of	9-9 - 9-10	Inspection documentation	9-1 - 9-2
Dry coating thickness, nondestructive		Inspection, presurface preparation	9-2
measurement of	9-8 - 9-9	Intercoat cleanliness and cure (assessment)	9-10
Electromagnetic probes	9-9	Irritants	10-2
Magnetic pull-off gages	9-8 - 9-9	Latex (see Binders, waterborne acrylic	
Dry film thickness (DFT), measurement of	9-8 - 9-9	emulsions)	
Drying oils	4-11	Lead, identification of existing coating	
Drying time	3-6	as containing	6-5 - 6-7
Environmental and worker protection		Chemical spot tests	6-6
regulations, development of	11-1	Laboratory analysis	6-7
Exposure service (see Service		Sampling procedure	6-7
environments)		X-ray fluorescence	6-6
Film-forming mechanisms	4-1 - 4-2	Lead regulations (see Regulations)	
Chemical crosslinked	4-2	Maintenance painting alternatives (for	
Oxidation	4-1	lead paint)	6-7 - 6-8
Solvent evaporation	4-1 - 4-2	Coating system selection	6-8
Fire protection/prevention	10-3 - 10-4	Coating system upgrading, spot	
Flammable/combustible liquids	10-2 - 10-3	touch-up, partial removal,	
Classification of	10-2	zone painting	6-8
Determining ventilation	10-3	Surface preparation alternatives	
Lower explosive limit	10-2	(for lead paint)	6-8
Upper explosive limit	10-2	Total coating removal and	
Flexibility	3-7	replacement	6-7 - 6-8
Fungicides	4-16	Maintenance painting options	6-4 - 6-5
Galvanizing	4-21 - 4-22	Complete removal and replacement	6-5
Hand-tool cleaning (SSPC-SP 2)	7-2	Spot repair (touch-up) and full	
Hardness, pencil, Barcol	3-7	overcoating	6-5
Hazardous material handling, coating		Spot repair (touch-up) only	6-4 - 6-5
materials	10-1 - 10-5	Maintenance painting, to achieve	6-1
Additives	10-2	Aesthetics	6-1
Binders	10-1	Corrosion protection	6-1
Organic solvents	10-1 - 10-2	Cost savings	6-1
Pigments	10-1	Energy conservation	6-1
Hazardous waste, disposal of	11-15 - 11-18	Facility upkeep	6-1
Definitions and testing of		Safety/identification	6-1
hazardous waste	11-16 - 11-17	Material safety data sheets (MSDS)	10-5
Generator requirements	11-17 - 11-18	Mixing, inspection of	9-5 - 9-7
Regulations	11-15 - 11-16	MSDS (material safety data sheet)	10-5
Holiday/pinhole detection	9-10	Near-white blast cleaning (SSPC-SP 10)	7-12
High-voltage holiday detectors	9-10	Oil-based alkyds	4-3
Low-voltage wet sponge, pinhole		Organic zinc-rich coating (see	
detector	9-10	Zinc-rich coatings)	
Immersion exposure (see Service		Paint sampling (see Sampling)	
environments)		Paint storage, mixing, and thinning	9-5 - 9-7
Impact resistance	3-7	Material receipt inspection	9-6
Inorganic zinc-rich coating (see		Mixing and thinning procedures,	
Zinc-rich coatings)		inspection of	9-6 - 9-7

Subject	Page	Subject	Page
Paint testing (see Testing paint, procedures of)		Ventilation	10-7
Performance tests (see Tests, performance of coating systems)		Safety, welding and cutting of coated steel .	10-7
Pigments	4-12 - 4-13	Sampling procedures (for lead paint identification)	6-7
Barrier pigments, aluminum flake, micaceous iron oxide	4-12 - 4-13	Service environments for USACE structures	5-12 - 5-15
Color pigments	4-13	Atmospheric, normal weathering	5-13
Extender pigments	4-13	Atmospheric, severe exposure	5-13
Hiding pigments	4-13	Immersion or frequent wetting exposure	5-13 - 5-14
Inhibitive pigments, chromates, lead, zinc	4-12	Interior exposure	5-13
Sacrificial pigments	4-13	Soil quality requirements	11-14 - 11-15
Polyurethanes (see Binders, urethanes)		OSWER Directive #9355.4-02	11-14
Powder coatings	4-19 - 4-20	Pre- and post-job sample analysis	11-14
Power Tool Cleaning (SSPC-SP 3)	7-2 - 7-3	Sampling and analysis	11-14 - 11-15
Power Tool Cleaning to Bare Metal (SSPC-SP 11)	7-3	Solvent Cleaning (SSPC-SP 1)	7-1 - 7-2
Procurement, paint (see Coating material procurement by)		Solvents	4-14 - 4-15
Regulations,		Alcohols	4-15
Air quality	11-11 - 11-13	Ester	4-15
CERCLA	11-16	Glycol ether	4-15
Environmental and worker protection .	11-1	Hydrocarbon solvents, aliphatics, aromatics	4-14
Hazardous waste	11-15 - 11-18	Ketone	4-15
NAAQS	11-11	Solvent safety	4-15
RCRA	11-15 - 11-16	Turpentine	4-14
Soil quality	11-14 - 11-15	Specifications, coating material by	
VOCs	11-12 - 11-13	Performance	3-2
Water quality	11-13 - 11-14	Product name or approved equal	3-2
Worker protection	11-1 - 11-11	Product name/manufacturer	3-1
Resins (see Binders)		Qualified products list (QPL)	3-2
Respirator selection	10-8 - 10-9	Standard specification/formulation	3-1
Respiratory protection	10-7 - 10-9	SSPC Paint Guide 5	6-2
Employee qualification	10-7 - 10-8	SSPC-SP 1 ("Solvent Cleaning")	7-1
Respirator issuance	10-9	SSPC-SP 2 ("Hand Tool Cleaning")	7-2
Respirator selection	10-8 - 10-9	SSPC-SP 3 ("Power Tool Cleaning")	7-2
Respirator use	10-9	SSPC-SP 5 ("White Metal Blast Cleaning")	7-12
Respiratory protection	10-6	SSPC-SP 6 ("Commercial Blast Cleaning") .	7-12
Roller application	8-1 - 8-2	SSPC-SP 7 ("Brush-Off Blast Cleaning") . .	7-12
Safety, abrasive blast-cleaning equipment (use)	10-5 - 10-7	SSPC-SP 10 ("Near-White Blast Cleaning")	7-12
Blast pots or pressure blast tanks	10-5	SSPC-SP 11 ("Power Tool Cleaning to Bare Metal")	7-3
Deadman controls	10-5	Surface cleanliness, inspecting	9-4 - 9-5
External couplings and blast hose	10-6	Burrs, slivers, and hackles, removal of	9-5
Helmets	10-6	Invisible contaminates, assessment of .	9-5
Nozzles	10-5	Visible contaminates, assessment of . .	9-4 - 9-5
Pot tender	10-5	Surface preparation, alternatives for lead paint	6-8
Protective clothing	10-6	Surface preparation, methods of	7-1 - 7-10
Safety, hand and power tools (use)	10-5	Abrasive blast cleaning - expendable abrasives	7-4 - 7-6
Safety, spray equipment (use)	10-7	Abrasive blast cleaning - recyclable abrasives	7-6 - 7-8
Respiratory protection	10-6 - 10-7	Chemical stripping	7-3
Spray gun operation	10-7	Hand-Tool Cleaning (SSPC-SP 2)	7-2

Subject	Page	Subject	Page
High pressure (5,000 to 10,000 psi)		Adhesion, tape, tensile, interpretation	
water jetting	7-3	of results	3-6 - 3-7
Low pressure (1,000 to 3,000 psi)		Chemical resistance	3-8
water jetting	7-3	Corrosion resistance, salt fog,	
Power Tool Cleaning (SSPC-SP 3)	7-2 - 7-3	prohesion, humidity	3-8
Power Tool Cleaning to Bare Metal		Field testing	3-9
(SSPC-SP 11)	7-3	Flexibility	3-7
Solvent Cleaning (SSPC-SP 1)	7-1 - 7-2	Hardness, pencil, Barcol	3-7
Ultra-high pressure ($\geq 15,000$ psi)		Impact resistance	3-7
water blasting	7-3	Thermal spray	4-20 - 4-21
Surface preparation standards and		Electric arc spraying	4-21
specifications	7-12 - 7-15	Plasma spraying	4-21
Aluminum surfaces	7-14 - 7-15	Powder flame spraying	4-21
Concrete surfaces	7-12 - 7-13	Wire flame spraying	4-20
Galvanized surfaces	7-13 - 7-14	Thinning, inspection of	9-5 - 9-7
Steel surfaces	7-12	Turpentines	4-14
Wood surfaces	7-15	Urethanes (see Binders, urethanes)	
Surface profile, measurement of	9-3 - 9-4	Vinyls (see Binders, vinyls)	
Survey, analyzing data	6-3	Viscosity	3-6
Survey, conducting maintenance painting	6-2 - 6-3	Volatile organic compounds (VOC)	4-19
Detailed (paint)	6-2	Volume solids	3-5
Midlevel (paint)	6-2	Water quality regulation	11-13 - 11-14
Minimal walk-through (paint)	6-2	40 CFR Subpart D, Parts 100 - 149	11-13
Tapes and wraps	4-22 - 4-24	No allowable release(s)	11-14
Butyl or EPDM vulcanized rubber		Permits	11-14
tapes	4-24	Reportable quantities	11-13 - 11-14
Coal tar and asphalt tapes	4-24	Wet coating thickness, measurement of	9-7 - 9-8
Heat shrink polyolefin tapes	4-24	White metal blast cleaning (SSPC-SP 5)	7-12
Petrolatum tapes	4-24	Work area control practices for lead paint	6-8 - 6-10
Polyethylene tapes	4-23	Final cleanup	6-10
Polyvinyl chloride tapes	4-23	Precogning	6-8
Test, interpretation and accuracy of		Restricted area	6-9
results (paint coatings)	3-9	Setup and isolation	6-9
Clarification of variances	3-9	Worker protection (regulations)	11-1 - 11-11
Variance thresholds	3-9	Action level/permissible exposure	
Testing paint, procedures of		limit (PEL)	11-1
Coating material characterization tests	3-5	Employee information and training	11-9
Density/weight per gallon	3-5	Exposure assessment	11-2 - 11-3
Drying time	3-6	Housekeeping	11-6
Infrared spectroscopic analysis	3-5	Hygiene facilities and practices	11-6
Nonvolatile content (weight solids)	3-5	Medical removal protection	11-8 - 11-9
Sampling methods	3-4	Medical surveillance	11-6 - 11-8
Viscosity	3-6	Methods of compliance	11-3 - 11-4
Volume solids	3-5	Observation of monitoring	11-11
Test patches, application	6-5	Protective work clothing and	
Tests, chemical spot (for lead		equipment	11-5 - 11-6
identification)	6-6	Recordkeeping	11-10 - 11-11
Tests, performance of coating systems	3-6 - 3-9	Respiratory protection	11-4 - 11-5
Abrasion resistance	3-7	Signs	11-9
Accelerated weathering	3-7		

Subject	Page	Subject	Page
X-ray fluorescence (for lead identification)	6-6	post-cured, water based;	
Zinc-rich coatings	4-17 - 4-18	self-cured, water based;	
Inorganic zinc-rich binders;		self-cured, solvent based	4-17 - 4-18
		Organic zinc-rich binders	4-18